

## EPA Region 1 Clean Water Act Inspection Data Entry Form: 3560EZ

Inspector:			Lisa Thuot	Date fo	rm c	completed:	8/5/20	15		
Section A:	Facility In	format	tion							
Inspection start date:		7/29/2015		Inspection end date (if more than one day):						
NPDES ID:		N/A	Federal facility?		No					
Name and	Location of	Facilit	y Inspected:							
	Name:		Magnan Brothers Home Farm							
	Address:		1380 Chester Arthur Rd.							
	City:		Fairfield	State:		VT	ZIP:	05455		
Facility Or	n-Site Repre	esentativ	ve #1:							
	Name:		Mark Magnan							
	Title:		Co-owner							
	Mailing address:		1380 Chester Arthur Rd., I							
	Phone #:		Enter text	Fax # / ema	ail:	Enter text				
Facility Or	n-Site Repre	esentativ	ve #2 (if necessary):							
	Name:									
	Title:									
	Phone #:			Fax # / em	ail:	Enter text				
Section B:	Complian	ce Mon	itoring Information							
Complianc	e Monitorir	ng Activ	rity Name:	CAFO						
Clean Wat	er Act Secti	on (cho	oose from only one of the fo	ollowing):						
	CWA §308	8[A][B]	: NPDES	ES Concentrated Animal Feeding				g Operations		
	CWA §311: Oil a		nd Hazardous Substances	Choose an	pose an item					
	CWA §404 Material	4: Perm	its for Dredge and Fill	Choose an item						
Complianc	e Monitorir	ng Type	::	Inspection						
Complianc	e Monitorir	ng Reas	on:	Agency Priority						
	If Agency	Priority	, then specify priority(s):							
		OECA	- CAFO							
		OECA	- CAFO Region Initiative	Areas	reas			$\boxtimes$		
		OECA - CSOs w/ < 50,000 service population								
		OECA	OECA - CSOs w/ >= 50,000 service population							
		OECA	OECA - MS4s Phase I							
		OECA - MS4s Phase II								
		Region 1 - Environmental Justice								
		Region 1 - Green Economy / Green								
		Region	n 1 - Industrial Laundries							
		Region 1 - Lead Poisoning								

Compliance Monitoring Agency Type:			EPA			
Was this a	Joint Com	pliance Monitoring Activity?	Yes			
	Which par	ty had the lead?	EPA			
	If State lead, what was the purpose of participation?		Choose an item or leave blank if N/A			

Section C: ICDS Information	
Did you observe deficiencies (potential violations) during the inspection?	Yes
Potential excess emission in violation of regulations:	
Potential failure to complete or submit a notification, report, certification, or manifest:	
follow a permit condition(s):	
follow a required sample monitoring procedure or laboratory procedure:	
follow or develop a required management practice or procedure:	
identify and manage a regulated waste or pollutant in any media:	
maintain a record or failure to disclose a document:	
maintain/inspect/repair meters, sensors, and recording equipment:	
obtain a permit, product approval, or certification:	
report regulated events such as spills, accidents, etc.:	
Potential incorrect use of a material (pesticide, waste, product) or use of an unapproved material:	
Potential violation of a compliance schedule in an enforceable order:	
If you observed deficiencies, did you communicate the deficiencies to the Facility during the inspection?	Yes
If yes, did you observe the Facility take any actions during the inspection to address the deficiencies noted?	No
If yes, what actions were taken? Choose an item	
If the Facility reduced pollution, what pollutant was reduced?	Enter text
Did you provide general compliance assistance in accordance with the policy on the role of the EPA inspector in providing compliance assistance during inspections?	Yes
Did you provide site-specific compliance assistance in accordance with the policy on the role of the EPA inspector in providing compliance assistance during inspections?	Yes

## Comments:

The inspection was conducted with Trevor Lewis (VT Agency of Agriculture). The farm has 700 mature dairy cows and 50 dry cows. No youngstock/heifers are located at this farm. The following issues were noted during the inspection: (1) The silage leachate collection system required maintenance/clean-up [solids/silage were accumulating in front of the screen to the collection system basin]; (2) The dry cow pasture borders a low, vegetated drainage swale; Trevor Lewis suggested placing additional electric fencing in this area; (3) Manure spreading records for 2014 were not in the farm's nutrient management plan (NMP); (4) During a crop field check, we observed erosion and sediment accumulation in the 25 ft. buffer area with the adjacent stream [located at a base of a hill]; Trevor Lewis said they will need a wider buffer in this hilly area in order to be in compliance with their NMP and the VT Agency of Agriculture's Medium Farm Operations (MFO) Permit.